

Pre-purchase Inspection Report

Chris Craft 20

#443

Created: 9 Sep. 2016

Last Updated: 19 Sep. 2016

Prepared for: Confidential



110

TESTS COMPLETED

99%

OVERALL SCORE

0

ACTIONS REQUIRED

RESPONSIBLE PERSON

- Rares Badrea
- Unassigned

ACTIONS ASSIGNED

- 0 (0%)
- 0 (0%)

	RESULT	COMMENTS
BOAT DETAILS		
1.1 Boat brand	Pass	Chris Craft
1.2 Boat model	Pass	Speedster 20
1.3 Boat length	Pass	20 ft / 6.1 m
1.4 Boat year of manufacture	Pass	2005
1.5 Boat HIN	Pass	Confidential
1.6 Number of engines	Pass	1
1.7 Engine make	Pass	Mercruiser
1.8 Engine model	Pass	5.0MPI
1.9 Engine year of manufacture	Pass	2005
1.10 Engine serial	Pass	Confidential
1.11 Engine hours	Pass	270
1.12 Drive model	Pass	Alpha One Gen 2
1.13 Drive year of manufacture	Pass	2005
1.14 Drive serial	Pass	Confidential
1.15 Boat registration	Pass	Confidential
1.16 Trailer make	Pass	Dunbier
1.17 Trailer year of manufacture	Pass	2005
1.18 Trailer registration	Pass	Confidential
1.19 Extras	Pass	
BOAT PICTURES		
2.1 Side view port	Pass	
2.2 Side view starboard	Pass	
2.3 Front view	Pass	
2.4 Rear view	Pass	
2.5 Engine bay	Pass	
2.6 Cockpit	Pass	
2.7 Cabin	N/A	
2.8 Toilet	N/A	
2.9 Master bedroom	N/A	



2.1 A



2.2 A



2.3 A




2.4 A



2.5 A



2.6 A



2.6 B



2.6 C

EXTERNAL CONDITION PAINT AND CORROSION

3.1 Engine block	Pass	
3.2 Gearbox	Pass	
3.3 Midsection	N/A	
3.4 Propeller	Pass	
3.5 Top cowling	N/A	
3.6 Exhaust manifolds	Pass	
3.7 Sacrificial anodes	Pass	
3.8 Extras	N/A	

CONTROLS AND CABLES

4.1 Remote control box operation	Pass	
4.2 Throttle cable	Pass	
4.3 Shift cable	Pass	
4.4 Start in gear protection	Pass	
4.5 Stop switch	Pass	
4.6 Buzzer	Pass	
4.7 Throttle disengagement	Pass	
4.8 Throttle friction adjustment	N/A	
4.9 Ignition key	Pass	
4.10 Prime start / choke	N/A	
4.11 Safety lanyard	Pass	
4.12 Extras	N/A	

GAUGES AND ELECTRICAL

5.1 Battery switch	Pass				
5.2 Start battery	Pass				
5.3 House battery	Pass	Battery charged retested			
	Action	Assignee	Due Date	Complete?	Action Comments
	Needs charge	Rares Badrea	19 Sep. 2016	✓ Yes	Put battery on charge and retest when full
5.4 Other batteries	N/A				
5.5 Shore power	N/A				
5.6 Genset	N/A				
5.7 Battery charger	N/A				
5.8 Inverter	N/A				
5.9 Dual battery charging setup	Pass				
5.10 Radio	Pass				
5.11 Stereo	Pass				
5.12 Radar	N/A				
5.13 Fish finder	N/A				
5.14 Bilge pump manual	Pass				
5.15 Bilge pump automatic	Pass				
5.16 Nav lights	Fail	Needs new bulb			
	Action	Assignee	Due Date	Complete?	Action Comments
	Check fuse	Unassigned	N/A	✓ Yes	Fuse ok
5.17 Stern light	Pass				
5.18 Cockpit lights	Pass				
5.19 Cabin lights	N/A				
5.20 Fresh water pump	N/A				
5.21 Deck wash	N/A				
5.22 Fans petrol fumes	Pass				
5.23 Speedo	Pass				
5.24 Tachometer	Pass				
5.25 Voltmeter	Pass				
5.26 Amp meter	Pass				
5.27 Fuel gauge and sender	Pass				
5.28 Oil pressure	Pass				
5.29 Water pressure	Pass				
5.30 Water temperature	Pass				


5.31 Trim	Pass	
5.32 Water tight connections on wiring	Pass	
5.33 Fuel management	N/A	
5.34 Spark plugs leads	Pass	
5.35 Charging system alternator	Pass	
5.36 Load test	Pass	
5.37 Starter motor	Pass	
5.38 Alternator belt	Pass	
5.39 Water alarm	N/A	
5.40 Windlass	N/A	
5.41 Extras	N/A	

STEERING AND HYDRAULICS

6.1 Steering helm	Pass	
6.2 Steering cable	Pass	
6.3 Hydraulic helm	N/A	
6.4 Hydraulic hoses	Pass	
6.5 Hydraulic cylinder	N/A	
6.6 Tilt tube condition	N/A	
6.7 Tilt tube water seal	N/A	
6.8 Trim	Pass	
6.9 Trim tabs	N/A	
6.10 Power steering belt	Pass	
6.11 Power steering pump	Pass	
6.12 Extras	N/A	

FUEL AND LUBRICANTS

7.1 Fuel tank	Pass	
7.2 Fuel vent	Pass	
7.3 Primary fuel filter	Pass	
7.4 Gearbox oil	Pass	
7.5 Engine oil	Pass	Engine Oil test report shows normal wear for engine hours and age
7.6 Lubricating points	Pass	
7.7 Extras	N/A	



7.5 A

BOAT

8.1 Gel coat paint	Pass	
8.2 Cover	Pass	
8.3 Bimini	Pass	
8.4 Carpet	Pass	
8.5 Safety	Pass	
8.6 Extras	N/A	
8.7 Boat material	Pass	Fiberglass

TRAILER

9.1 Frame	Pass	
9.2 Rollers	Pass	
9.3 Bunk boards	N/A	
9.4 Winch	Pass	
9.5 Jockey wheel	Pass	
9.6 Axle	Pass	
9.7 Bearings	Pass	
9.8 Coupler	Pass	
9.9 Tyres	Pass	
9.10 Coupler	Pass	
9.11 Lights	Pass	
9.12 Extras	N/A	

COMPRESSION TEST

10.1 Cyl 1	Pass	175 psi
10.2 Cyl 2	Pass	175 psi
10.3 Cyl 3	Pass	175 psi
10.4 Cyl 4	Pass	175 psi
10.5 Cyl 5	Pass	175 psi
10.6 Cyl 6	Pass	175 psi

10.7 Cyl 7	Pass	175 psi
10.8 Cyl 8	Pass	175 psi
WATER TEST		
11.1 Operating temperature	Pass	
11.2 Thermostat operation	Pass	
11.3 Trim tabs	N/A	
11.4 Steering	Pass	
11.5 Engine height - outboard only	N/A	
11.6 Propeller size	Pass	21 pitch
11.7 Trailer setup for launching	Pass	
11.8 Cruising speed RPM	Pass	3750
11.9 WOT RPM	Pass	4800
11.10 Max Speed	Pass	42 MPH
11.11 Extras	N/A	

FINAL COMMENTS

Boat in very good overall condition

SIGNEES

